SDMS US EPA Region V

Imagery Insert Form

Document ID:

Some images in this document may be illegible or unavailable in SDMS. Please see reason(s) indicated below:

X	Illegible due to bad source documents. Image(s) in SDMS is equivalent to hard copy.
الحصا	Specify Type of Document(s) / Comments:
	SMALL HOLES IN TEXT IN SOME PLACES
	Includes COLOR or RESOLUTION variations. Unless otherwise noted, these pages are available in monochrome. The source document page(s) is more legible than the images. The original document is available for viewing at the Superfund Records Center.
	Specify Type of Document(s) / Comments:
	Confidential Business Information (CBI). This document contains highly sensitive information. Due to confidentiality, materials with such information are not available in SDMS. You may contact the EPA Superfund Records Manager if you wish to view this document.
	Specify Type of Document(s) / Comments:
	Unscannable Material: Oversized or Format. Due to certain scanning equipment capability limitations, the document page(s) is not available in SDMS. The original document is available for viewing at the Superfund Records center.
	Specify Type of Document(s) / Comments:
	Document is available at the EPA Region 5 Records Center.
	Specify Type of Document(s) / Comments:

Rev. 07/10/02

ESD

EPA REGION III OA DIRECTIVES

HWMD

Bulletin No. OAD009

Date: April 23, 1990

FIELD FILTRATION POLICY FOR MONITORING WELL GROUNDWATER SAMPLES REQUIRING METALS ANALYSIS

The objectives of this directive are: (1) to formally state Region III RCRA and CERCLA policy which requires both filtered and unfiltered groundwater samples for metal analyses; (2) to outline appropriate exceptions to the state it policy and (3) to provide technical direction for the field filtration procedure.

and a surgle copy of this directive is provided to the individual designated to represent the contractor. It is the responsibility of that and a sustribute the directive within the contractor organization to appropriate project managers and field personnel.

in the sample. Filtered samples represent dissolved metals concentration and are often more representative of an orde contamination (see exceptions below). Monitoring wells sometimes produce turbid water (water containing suspended solids). The turbidity can be due to disruption of the adjacent geologic formations during well purging or poor design and initial development of the well. When particles containing metal species are suspended into the groundwater and are not removed, they dissolve when the sample is preserved to a pH < 2. High levels of manganese, and iron in unfiltered samples often indicate the presence of these particles. Without incentrations of this mobile metal contamination in the groundwater are often over estimated. The containing it is necessary to take both filtered and unfiltered samples to fully characterize the distribution of metals between particulate and distribution preservation for dissolved metals samples must be performed after filtration. Because the or take to distribution must occur immediately after sampling.

The exceptions to the policy requiring both filtered and unfiltered samples are:

- Site specific geologic conditions where groundwater may transport large particulates and constrained samples are representative of mobile groundwater quality (for example, karst terrain or close graves (autos).

 These site conditions must be fully discussed and documented in the Quality Assurance Project I ket (QAP)?
- 2. When there is sufficient historical data (a minimum of four consecutive quarters) from the same anonitoring wells that are to be sampled, then these wells may fall into one of the folloring exception categories:
 - a. If the historical information shows that the purging and sampling methods are the same as the methods to be used at future sampling events, then either likered or unfiltered samples as appropriate to the mistorical data are acceptable for future sampling in these wells.
 - b. If the historical information shows inconsistency between the filtered and unfiltered data, and high levels of aluminum are present in the unfiltered data, only filtered samples are needed.

NOTE: Extrapolation of historical data from a limited number of wells to all the wells at the site is a without a clearly justified rationale. All deviations from taking BOTH filtered and unfiltered grounds samples for metals must be fully described and justified in the QAPJP.

TECHNICAL GUIDANCE FOR FILL RATION OF MONITORING WELL SAMPLES FOR METALS AND ALISIS

Designate an area in which the free environment. When filters Use either a glass or plant and samples.

tion process is to take place. This area must have an element and dustparatus is not in use, keep it devere I to protect from unborne particles.

Imparatus. Stainless steel is unaccipiable since it can contaminate the

- - 1.45 micron filter is the required pore size for filtration. Other pore-size filters may be appropriate for site conditions. However, deviations from the 0.45 micron pore size must be justified and documented in APJP and field notebook. The polycarbonate membrane type is recommended. For highly turbid water, alean glass fiber filter may be used as a "pre-filter". When a pre-filter is used, place it ou top of the 0.45 exercin filter, then filter the sample using the normal procedure. Dispose of the pre-filter and record a general denoting of the turbidity of the sample in the field notebook.
- 4. Each filter and filtration apparatus must be prepared before use since they often contain trace amounts of metals. Filtration with approximately 20 ml of a 25% nitric acid (HNO₂) solution (3 parts water and 1 part and) followed by three 20 ml rinses of trace metal free deionized (DI) water is required to remove any trace amounts of metals. The filtered liquid is then discarded before filtering each sample. Use the same DI water and dilute mixic acid solution (i.e., prepared from the same source, lot number and/or batch) to prepare the filters for all samples and the field blanks.
- in the substitute of the laber of the laber
- 6. All warranamples, including surface water, filtered and unfiltered groundwater, and blanks must be presented to a pH <2 with HNO₃. Use a high quality acid such as Baker instra-Analyzed or equivalent. NOTE: Reagent grade acid is not acceptable. Verify that the pH of each sample is <2 with narrow range (0 to 2) pH paper.
- 7. Document the lot number and manufacturer of the acid, the deionized water, and the filters in the field will live in. This documentation will facilitate tracing the source of contamination when the data indicates the populatily of a contamination problem.
- 3. Mountaining wells with a very high concentration of solids (evidenced by a slow filtration and) whould be note. In the field notebook. This may indicate an improperly installed monitoring well.

DATA INTERPRETATION

The concentration of a dissolved metal (filtered sample) should not exceed its concentration as a total metal (infiltered sample). If the dissolved fraction exceeds the total fraction by a small amount, it may be attributable to analytical variability. Typical problems and their possible causes are listed below:

- .. The dissolved concentration is higher than the total:
 - o When dissolved iron, zinc, aluminum, and copper are higher, then the filters may be a source of contamination. Investigate the rinsing procedure used for filters.
 - When nearly all dissolved metals are higher, then sample mislabeling is a possible source of error.

 Investigate the sample labeling procedure.
- 2. If the sample results are erratic, investigate the time lapse from sampling to filtration.

. . . .